

COOPERATION TO INCREASE THE PROFITABILITY OF AGING GERMAN WIND FARMS

Effective Measures for Economic Operation after the End of the full Maintenance Contract and during Continued Operation

Bernd Höring, 8.2 Monitoring GmbH

Cooperation – Stronger Together

8.2 | The Experts in Renewable Energy

- Company within the 8.2 Group
- 25 years of CMS experience in Wind
- CMS-Hardware, delivered by partners
- VibraLyze**PRO** – Multi-Brand CMS analysis software
- 8.2-**Inspect**-App – inspection software
- Analysis, Inspections, RCA, DD & Consulting
- Global business with 130 employees
- Independent



- Company of the BP Group
- 30 years rotating machinery engineering and software development in Wind
- eco**CMS** – advanced sensing hardware
- fleet**MONITOR** – CMS independent cloud based analytics solutions
- field**PRO** – service & inspection software
- Global business with over 80 employees of those 10 Software Development Engineers
- Independent

Condition Monitoring System 4.0

8.2 | The Experts in Renewable Energy

In partnership with



**5th ANNUAL WIND TURBINE
TECHNICAL SYMPOSIUM**

1.050 participants
(US / EU / APEC)

Existing turbines / Germany

- Currently approx. 54 GW Onshore / 8 GW Offshore or 30,000 WTG in total
- 1/3 of the turbines are older than 15 years !
 - **Dismantling**
 - **Repowering**
 - **Continued operation after 20 years**
- The risk of damage increases with age
- How can economic operation be ensured?

Condition Monitoring System 4.0

- Next generation CMS
 - **ecoCMS** with 3D-MEMS sensors
 - Development based on newest IoT-Technology
 - Cloud-based analysis software – **fleetMONITOR**
- Proven analysis service by 8.2
- Intelligent SCADA Data analyses software – **AI HUB**
- Service life extension through main bearing flushing

Synergy for the benefit of our customers

- Best cost/benefit ratio through ecoCMS retrofit, even for sub megawatt class
- Integration of all status information fleet**MONITOR**
- Detection of anomalies before they come to a standstill through intelligent SCADA analysis - **AI Hub**
- Reducing of OPEX costs up to 15 %
- Reliable information to help asset management make the right decisions

ecoCMS – Technology



3D-MEMS (SD)



3D-MEMS (HD)
acceleration sensor

- 3D-MEMS (Micro-Electronic-Mechanical-Sensor), sampling rate up to 25.600 S/s, including temperature sensor for bearings
- 1x inductive proximity sensor rpm0 for speed measurement
- 1x optical proximity sensor rpm1 for localization of the faulty rotor blade
- ecoCMS unit for data acquisition and pre-processing
- Internet connection via local network or 4G router
- Secure communication via VPN to wind farm network



Speed sensor, rpm0




Rotor position, rpm1



ecoCMS unit




Data processing & Work flow



Usual data analysis by 8.2 - fleetMONITOR




Work place



Dashboard – wind farm overview

Alert ID	Alert Message	Alert Type	Alert Status
1	3.0-MS5 CW-01-446-10	MS5	Clear-15:55
2	3.0-MS5 DW-Health index (D5)	MAB	Clear-15:55
3	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
4	3.0-MS5 DW-Health index (D6)	MAB	Clear-15:55
5	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
6	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
7	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
8	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
9	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
10	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
11	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
12	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
13	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
14	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
15	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
16	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
17	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
18	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
19	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
20	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
21	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
22	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
23	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
24	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
25	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
26	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
27	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
28	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
29	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55
30	3.0-MS5 Big-DW-05021-8p2	MAB	Clear-15:55


Alert message



Analyses by Experts



Trend with Report marker



Report / Recommendation

8.2





CMS retrofit E-70 / Sensor positions




Main bearing A, 12h



Main bearing A, 9h



Main bearing B, 12h und 3h



Main frame/Tower, 12h




Speed sensor, rpm0



Rotor position, rpm1



Retrofit example – E-82 / GE1.5




3D-MEMS +
temp. sensor

ecoCMS
smart – fully digital
over 5.000 x installed






“Next generation” SCADA-Monitoring



AI - and MachineLearning (ML) algorithms coupled with proven engineering models

SCADA / AI HUB – Case study



AI and Machine Learning (ML) algorithms coupled with proven engineering models to enable

- early detection of anomalies
- a proactive maintenance planning
- a prevention of damage progression
- the reduction of machine downtime

Lifetime extension of main bearing

- Main bearings are durable, but costly components, if damage occurs
- With ecoCMS and fleetMONITOR main bearings can be monitored safely
- In case of a detected damage, the operating time can be extended by many months with main bearing grease flushing
- The main bearing replacement can thus be optimally planned

Main Bearing Grease Flush - Technology

- Process with turbine-specific adapters
- Uses a specific light oil as flushing medium
- Cleans bearings from >95% of old grease and deposits
- Usually completed in one shift
- Closed process, no contamination of the plant
- Rinsing devices all bundled /Lift bags
- Patent protected by ONYX technology



Main bearing flush - results



before




during



after



Case study – Main bearing flushing



Activity	Comment
A	Fault detection by ecoCMS Service report
B	Inspection video endoscopy Damage confirmed
C	1 st MB grease flushing Abrasion, particles removed
D	Inspection Videoendoscopy Damage confirmed
E	2 nd MB grease flushing Abrasion, particles removed
F	MB exchange Combined repairs





8.2 | The Experts in Renewable Energy

In partnership with



8.2 Monitoring GmbH
Bernd Höring
Brandstwiete 4
20457 Hamburg

I will be happy to answer your questions

bernd.hoering@8p2.de
M +49 173 540 44 53

Link: <https://onyxinsight.com/monitoring-hardware/>
Link: <https://onyxinsight.com/monitoring-software/>